

K-22 ASSEMBLY INSTRUCTIONS

PART LIST

1-STRAIGHT ARM

1-SLANT ARM

1-IRON SHEET

1-LID


1-BASE

1-FRAME

2-BOLTS

BOLTS ARE SCREWED
IN PLACE

STRAIGHT ARM



← SLANT ARM

← FRAME

← IRON SHEET

← LID

← BASE

← BOLT

