

# HT20 ASSEMBLY INSTRUCTIONS

PART LIST	
1-BASE	
1-BOLT	
1-LEVER	
5-HALLSTANDS	
10-BOLTS	
10-TUBE JACKETS	
BOLTS ARE SCREWED IN PLACE	

